Trade of Metal Fabrication		
Module 2:	Thermal Processes	
Unit 9:	Tungsten Arc Gas Shielded Welding (Stainless Steel)	
	Phase 2	

Table of Contents

List of Figures	
List of Tables	4
Document Release History	5
Module 2 – Thermal Processes	6
Unit 9 – Tungsten Arc Gas Shielded Welding (Stainless Steel)	6
Learning Outcome:	6
Key Learning Points:	6
Training Resources:	7
Key Learning Points Code:	7
TIG MMA Square Wave	
Electrode Protrusion	
Preparation of Electrode Ends	9
Tungsten Arc Gas Shielded Welding	
Arc Starting	
Applications	
Depositing Straight Runs	
Striking and Breaking the Arc	15
Fusion with Filler Metal	
Self Assessment	
Index	17

List of Figures

Figure 1 - 250 a.c./d.c. TIG MMA Square Wave with OC/CV Feeder	8
Figure 2 - Electrode Protrusion	8
Figure 3 - Preparation of Electrode Ends	9
Figure 4 - Characteristics of a.c. and d.c. Arcs	10
Figure 5 - Tungsten Arc Gas Shielded Welding Applications	12
Figure 6 - Fusion with Filler metal	15

List of Tables

Document Release History

Date	Version	Comments
02/11/06	First draft	
13/12/13	SOLAS transfer	

Module 2 – Thermal Processes

Unit 9 – Tungsten Arc Gas Shielded Welding (Stainless Steel)

Duration – 16 Hours

Learning Outcome:

By the end of this unit each apprentice will be able to:

- Safely set up and weld using a TIG/TAGs welding plant on stainless steel
- Select and prepare a tungsten electrode
- Select and adjust welding current to suit stainless steel
- Identify and correct weld defects
- Weld a series of exercises on stainless steel
- State the safety precautions to be observed when TIG welding

Key Learning Points:

Rk Sk	Weld techniques.
Rk Sk	Tungsten selection and preparation - tungsten protrusion (stick out).
Rk Sk	Plant settings and adjustments.
Rk	Weld defects (e.g. porosity, weld profile, lack of penetration).
Rk Sk	Torch and rod manipulation.
Rk	Purging of roots.
Rk Sk	Speed of travel when welding.
Rk Sk	Distortion Control (chills).
Rk Sk	Post weld cleaning.
н	Safety procedures and precautions - safe work area, P.P.E.
Р	Communication, work planning/quality.

Training Resources:

- Fabrication workshop facilities
- T.A.G. Weld plant and equipment, filler rods
- Welding booths and extractors
- Handouts and notes
- Safety clothing and equipment
- Materials as stated on exercises
- Examples of good and bad welds

Key Learning Points Code:

M = MathsD = DrawingRK = Related Knowledge Sc = ScienceP = Personal SkillsSk = SkillH = Hazards

TIG MMA Square Wave



Figure 1 - 250 a.c./d.c. TIG MMA Square Wave

Available voltages: 230/380/415/500 a.c.

50 Hz OCV 80

Welding mode switch 5 310 A, a.c. or d.c.e.n., d.c.e.p.

Pre and post flow gas 250 A at 40° duty cycle Balance control penetration/cleaning Arc force control (soft or digging arc)

Electrode Protrusion



Figure 2 - Electrode Protrusion

No gas lens. In awkward places protrusion can be increased. Gas shield must cover area being welded.

Preparation of Electrode Ends

- 1. The working tip of the electrode should be ground to provide a point. For this purpose a silicon carbide wheel, grade 0 to M 60 grain, should be kept and not used for other work.
- 2. For D.C. welding a sharp point is desirable. The length of the taper for electrode sizes up to 1/8" (3.0 mm) should be about three times the diameter. For electrode sizes over 1/8" (3.0 mm) it should be about twice the diameter.
- 3. For A.C. welding a 'balled' point is desirable. The end should be pre-chamfered at an angle of about 45° leaving a blunt point of a diameter about half that of the electrode diameter. Before use an arc should be struck on scrap parent metal to 'ball' the end of the electrode.



Figure 3 - Preparation of Electrode Ends

Tungsten Arc Gas Shielded Welding

This process is a method of welding whereby an electric arc is maintained between a virtually non-consumable tungsten electrode, in an atmosphere of pure argon, with or without small additions of other beneficial gases. The gas shield prevents weld metal contamination by the atmosphere. The surface of aluminium alloys is covered by a refractory high melting point film of oxide which must be removed before a satisfactory weld can be made. A filler wire may also be added at the leading edge of the molten pool to form the weld. It is one of the characteristics of an alternating current arc that it removes this tenacious oxide during the welding process. Figure 4 shows the characteristics of a.c. and d.c. arcs.

Arc Starting

To initiate the arc for welding the two most common methods are:

High Frequency (H.F.) A series of high-voltage high-frequency sparks are superimposed on the main welding current so that, at the press of a switch, they pass from the tungsten to the work and so ionise the air gap (break down the resistance) and allow the welding current to create an arc. This avoids touching the plate with the tungsten and avoids contamination. The H.F. may be continuous for a.c., and for d.c. used only when the arc has been extinguished.

Surge Injection is another method of arc starting which also uses a high-voltage high-frequency spark.



Figure 4 - Characteristics of a.c. and d.c. Arcs

Heat distribution	Plate Electrode ² / ₃ ¹ / ₃	Plate Electrode ¹ / ₃ ² / ₃	Equally distributed with a 50 c/s supply, the electrode is positive for 1/100 sec, then negative for 1/100 sec.
Electrode composition	2% thoriated tungsten ground to a sharp point approx.60°.	_	1 % zirconiated tungsten ground to 45° with a blunt end.
Applications			
Welding carbon and stainless steels, titanium, nickel, copper and respective alloys.		Seldom used and never for thick materials	Used for welding aluminium and magnesium and their alloys.
Explanation of	characteristics		
d.c. negative tungsten The electrode remains cool but		d.c. positive tungsten	a.c. tungsten changing polarity
the oxide film is unbroken (hence no good for aluminium). Resulting weld is narrow with deep penetration resulting from bombardment of the plate by the electrons.		The oxide film on the plate is lifted and disrupted by the electron flow from the plate. Overheating of the electrode with tungsten inclusions and wide shallow weld results. (Not advised for welding any thick materials).	The oxide film is disrupted and removed during the time the electrode is positive, causing the electrode to overheat. This is followed by a period when the electrode becomes negative and cools down but with no oxide removal but with $\frac{2}{3}$ of the heat in the plate (most suitable for aluminium).

Applications

The T.A.G.S. welding process is used where high-quality neat-looking welds are required, and is economical for thicknesses up to 6 mm. For thicknesses greater than 6 mm, M.A.G.S. welding is usually used or other metal arc welding processes. Root runs in pipe joints either with or without fusible inserts are put in using T.A.G.S. welding because the penetration can be controlled to give a smooth flush finish. After inspection the remainder of the joint is completed using quicker methods. Figure 5 shows the electrode shapes used.



Figure 5 - Tungsten Arc Gas Shielded Welding Applications

Depositing Straight Runs

Example Procedure EP43

- 1. Establish small pool of molten metal near right-hand edge of sheet, holding torch vertical.
- 2. Decrease the electrode angle to 70° - 80° .
- 3. Hold filler rod in left hand, between the fingers and thumb, pointing at the front edge of the molten pool and at an angle of $10^{\circ}-20^{\circ}$.
- 4. Allow the arc heat to melt a little metal from the end of the filler rod and start the leftwards movement of the torch.
- 5. Always keep the filler rod end within the argon shroud, making contact with the weld pool but not with the electrode when adding filler metal.
- 6. Steady addition of filler metal gives even deposition. The rate of travel leftwards should be coordinated with melting of filler rod to control size of bead and extent of penetration.

Repeat the procedure until separate straight runs of even shape and width can be produced at will with a consistent arc length of less than 1/8'' (3.0 mm). Do not allow parent metal to become over-heated.

Material	16 s.w.g. (1.5 mm) stainless steel, 1 off, min. 4" (10.0 cm) x 6" (15.0 cm).
Preparation	Clean surface.
Assembly	Support sheet in flat position, long axis, and parallel to bench front.
Electrode	1/16" (1.5 mm)
Argon	5-8 ft. ³ /hr.
Current	50-70 amperes
Filler	1/16" (1.5 mm)



Keep the filler rod end always within the argon shroud and resting on the parent metal

Material	16 s.w.g. (1.5 mm) aluminium, 1 off, min. 4" (10.0 cm) x 8" (20.0 cm).
Preparation	Surface cleaned immediately before welding.
Assembly	as for EP 43.
Electrode	3/32" (2.5 mm)
Argon	8-12 ft. ³ /hr.
Current	50-75 amperes
Filler	3/32" (2.5 mm)

Example Procedure EP 44

- 1. Commence welding at the right-hand edge of the sheet.
- 2. The torch and filler rod should be held in the same manner as for EP43, taking great care that the filler rod end is kept within the argon shroud.
- 3. The weld pool will not be so clear as when welding corrosion-resistant steel but the slight oxide film will be disintegrated and removed so that it causes no difficulty in observing the weld pool.
- 4. Co-ordinate the leftwards movement and the addition of filler metal to build up a reinforcement bead of even height and width.

Visual Examination

Examine deposited beads and note any variations in width or height of run or depth of fusion into parent metal. These may be caused by variations in arc length, rate of travel, rate of addition of filler metal. Assess causes and take appropriate corrective action.

The reverse side of the sheet should indicate traces of penetration without any burnthrough.

Striking and Breaking the Arc

Fusion with Filler Metal

Having mastered the basic skills using D.C. equipment for the welding of stainless steel (or mild steel), practice should be obtained using A.C. equipment for the welding of aluminium.

It will be necessary to make adjustments to the rate of torch travel and the rate of filler metal feed. There will be observable differences in arc characteristics.



Figure 6 - Fusion with Filler metal

Self Assessment

Questions on Background Notes - Module 2.Unit 9

No Suggested Questions and Answers.

Index

Ε

Electrode Protrusion, 9

Ρ

Preparation of Electrode Ends, 11

S

Striking and Breaking the Arc, 17 Fusion with Filler Metal, 17

Т

TIG MMA Square Wave with OC/CV Feeder, 9 Tungsten Arc Gas Shielded Welding, 12 Applications, 13 Arc Starting, 12 Depositing Straight Runs, 15